

# Israel Beetison House

Conditions and Structural Assessment

Prepared by Melissa Gengler  
and Mike Eisenbarth



# History and Background Information

---

- Built by Israel Beetison in 1874-75
- Listed in the National Register in 1976
- Sold in 1999 and vacant since









# Conditions Assessment

- On-site evaluation conducted in February 2022 with representatives from consultant team, city, and developer
- Thorough investigation of visible portions of the building to evaluate issues with structural integrity and condition of historic fabric
- No finishes were removed and observations did not extend to hazardous materials such as asbestos, mold, or lead paint.

# General Building Information

---

- Two-story, wood and stone framed building with basement
- North portion is 1 ½ story with basement
- All walls are limestone with finished exterior faces and 18 inches thick.





# Basement

---

- Two lines of wood posts and beams that run along a north/south axis down the center of the main house
- Unmilled timber consisting of round logs of varied diameter that support full 6X6 beams.



# Basement Issues



# First Floor

- Framed with full 2x8s spaced 12 inches on center.
- Joist bearing along the east basement wall has shifted and the wood sill plate is separating from the wall
- Ceiling originally plaster with wood lathe fastened directly to bottom of second floor framing



# Second Floor

---

- Framed with full 2x8s.
- Ceiling joists are full 2x4s spaced a max of 24 inches on center.
- These are supported by exterior walls and wood-framed walls support the cupola floor and roof framing.
- Portion of floor rotted, located directly beneath hole in roof.





# Roof

- Hipped main roof framed with full 2x6 rafters.
- Areas have failed and holes through the main roof at the east and south hips and the west face of the north gable.
- Some joists exhibit rot.
- Roof over northwest porch severely deteriorated





# Exterior Stone

- Three chimneys, none are capped
- Cracks in masonry around chimneys
- Large crack in the NW corner of main house
- Arches over windows require repair (14)
- Weathered joints require repointing
- Cracked stone lintel over basement stair








# Conditions

- Wood trim removed and historic finishes no longer present
- Interior physical integrity no longer exists
- Years of exposure and water infiltration has deteriorated interior features such as wood flooring and plaster
- Extensive vandalism









## Conclusions and Recommendations

- No historic character defining features remain within building.
  - Structural stabilization and total renovation required.
- Replace roofing and deteriorated skip sheathing
  - Strengthen/replace damaged wood framing
  - Rebuild masonry arches and repair or replace stone lintel over basement stair
  - Repoint
  - Shore and rebuild joist bearing
  - Enclose building envelope
  - Install steel caps over chimneys

# General Cost Concept

- \$200-\$250 per square foot (based on neighboring construction costs=\$500,000)
  - Additional Structural Repairs \$70,000-\$100,000
  - Roughly \$1M
  - Costs may vary up or down depending on finishes and unforeseen issues.
- 
- Masonry \$20-\$25/sf on affected areas
  - Joist sistering could be \$150 per joist
  - Joist bearing at east basement wall \$2500-\$4000
  - Structural repairs estimate (including masonry) may be \$35-\$50/sf